

Test Report

No. CANML1721954801

Date: 08 Nov 2017

Page 1 of 4

GUANGDONG GONGLI BUILDING MATERIALS CO., LTD

WEST OF THE JIAHE NORTH ROAD,LUBAO TOWN,SANSHUI FOSHAN CITY GUANGDONG,CHINA

The following sample(s) was/were submitted and identified on behalf of the clients as :
ASA synthetic resin roof tile (spanish style roof tile)

SGS Job No. : GZIN1711052773PC - GZ
Date of Sample Received : 04 Nov 2017
Testing Period : 04 Nov 2017 - 08 Nov 2017
Test Requested : Selected test(s) as requested by client.
Test Method : Please refer to next page(s).
Test Results : Please refer to next page(s).

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Zmguan

Zm guan
Approved Signatory



Test Report

No. CANML1721954801

Date: 08 Nov 2017

Page 2 of 4

Test Results :

Test Part Description :

Specimen No.	SGS Sample ID	Description
SN1	CAN17-219548.001	White material

Remarks :

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Elementary Analysis

Test Method : With reference to IEC62321-5:2013, analyzed by ICP-OES .

<u>Test Item(s)</u>	<u>Unit</u>	<u>MDL</u>	<u>001</u>
Lead (Pb)	mg/kg	2	19

Notes :


- (1) IEC 62321 series is equivalent to EN 62321 series
http://www.cenelec.eu/dyn/www/f?p=104:30:1742232870351101:::FSP_ORG_ID,FSP_LANG_ID:1258637,25.



ATTACHMENTS

Pb Testing Flow Chart

- 1) Name of the person who made testing: Edith Zhang
- 2) Name of the person in charge of testing: Bella Wang
- 3) These samples were dissolved totally by pre-conditioning method according to below flow chart.



Sample photo:



SGS authenticate the photo on original report only

*** End of Report ***